

Nov 25, 2021

# QUALITY INSPECTION REPORT

---

PV Supervision,


Automatic PV supervision  
from thermographic pictures

## CLIENT

My client name

Address

City, Country



Powered by  
**PV Supervision**  
pvsupervision.com

# THERMOGRAPHY IMAGES



PV panel




Junction box




Hot spot

IMAGE	DETECTED PROBLEMS
-------	-------------------




**4 Hot spots**

20171122\_124319.jpg




**3 Hot spots**

20171122\_124315.jpg




**No issues found**

20171122\_124317.jpg



20171122\_124318.jpg

**No issues found**



20171122\_124320.jpg

**No issues found**